1999 Dodge RAM 3500 PICKUP

Submodel: | Engine Type: L6 | Liters: 5.9

Fuel Delivery: FI | Fuel: DIESEL

DTC Code P1690

DTC Code:

P1690

Description: Fan Control Relay

Probable Causes:

1. Sensor or solenoid faulty

Connector terminal contact is damaged or corroded
Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
Update control unit software - Check for the latest control unit update

5. Powertrain or Engine Control Module faulty