

2007 Dodge RAM 2500

Submodel: LARAMIE | Engine Type: L6 | Liters: 6.7

Fuel Delivery: FI | Fuel: DIESEL

DTC Code P0973

DTC Code:

P0973

Description: Shift Solenoid "A" Control Circuit Low

Probable Causes:

1. Sensor or solenoid faulty
2. Connector terminal contact is damaged or corroded
3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
4. Update control unit software - Check for the latest control unit update
5. Powertrain or Engine Control Module faulty
6. Battery voltage low
7. Transmission system malfunction