

Blocker package FAQ/Help page

Please read this entire Document if you are having problems with the Blocker package as most questions are answered here. Do not call if you are having problems, send an email as noted below. It is critical to copy the email message to BOTH addresses listed in the last Q&A .

For more information about the function of the Duramax EGR system please reference this page:

http://www.kennedydiesel.com/docs/Duramaz_LLY_LBZ_Emissions.htm

Q: What codes will the Blocker package/Fingers Stick block?

A: Without the FS, people will typically see P0401 and P0404 codes when installing after market exhausts or blocking the EGR. These are the codes related to the sensed EGR flow is not being within expected values. The Finger Stick does not actually block any codes. Instead, it modifies the signal from the MAF sensor based on the EGR valve's position. This provides the ECM with the values it expects for intake air flow. Therefore, the Finger Stick is a signal modifier, not a code blocker, and requires an operational EGR valve to work properly.

Q: Can I use Scotch lock wire taps?

A: They are not recommended. Soldering is preferred.

Q: How do I know which wires to use?

A: Wires should always be traced back to their connector. The wire's position in the connector determines it's function, not the color! GM has a bad habit of using the same color several times in the same harness and even changing the color. It is up to the installer to take the time to verify where the wires go.

Q: Which wires do I cut?

A: Only the wire for the MAF signal needs to be cut and separated. All others are simple taps into the wire.

Q: My plate will slide in completely or fit flush.

A: The bottom of the plate frequently catches on the bottom of the main hole through the flanges and gasket. Filing a little taper on the bottom edge of the plate helps. It is not catching on the studs.

Q: Why do I have a whistle/squeal?

A: You have a leak. If re-tightening the flange does not stop it, you might have damaged the gasket. Remove the plate and coat it with “Form a Gasket Copper”. Let that set and re-install.

Q: Can I use the plate without the stick?

A: Yes, but you will set codes and the SES light will illuminate.

Q: Can I use the stick without the plate?

A: Yes, though not recommended. The plate stops the flow of soot back into the engine.

Q: I installed the stick, but now have SES light on. What do I do?

A: Very first thing is to check your installation. Ask a buddy to check for you. A fresh set of eyes frequently pick up on a problem that you have been staring at for hours. If that doesn't work, get the codes read. When you read the codes, write down the EXACT number as this means more to use than the description.

Important note:

There have been recent (early 2007 calendar year) software updates from GM to correct for numerous DTC's that occur in completely stock 2006/7 LBZ and LLY trucks. It is recommended that these updates be applied before any further troubleshooting is done. The Q and A below assumes that you have already done this.

Q: I have DTC P0299.

A: You didn't install the blocker plate did you?

Q: I have DTC P0101.

A. This indicated a problem with the installation or the stick. In short, it isn't working at all.

Q: I have DTC P0401 and/or P0404.

A. Stick is working, but there is a bad connection to the EGR. (blue wire)

Q: I have a DTC P0402

A: It is likely that you have an aftermarket air intake. Try switching back to the OE intake. This will likely cure it.

Q: I have a DTC P0403

A: P0403 is an indication of a problem with the EGR Servo motor electronics and is unrelated to the Finger Stick which will neither cause nor cure this code.

Q: I have DTC P046C

A: The EGR valve itself is having problems. Remove the stick and plate. You will be going to the dealer to get it repaired. The Stick needs to have a functioning EGR valve to do its work.

Q: I have read all of the above, checked my connections and still am having problems. What do I do now?

A: Send a detailed email note to john@kennedydiesel.com **AND** fingers@jemcelravy.com In this email you must include your complete contact information, vehicle specifics, codes being set, symptoms, and additional vehicle modifications. This is all necessary so that we can make an accurate assessment of the situation.

Please read this entire Document if you are having problems with the Blocker package as most questions are answered here. Do not call if you are having problems, send an email as noted above. It is critical to copy the email message to BOTH addresses listed.

Note: It is quite rare to have an actual failed device. Unfortunately it is relatively common to have problems with the installation of this device.

For more information about the function of the Duramax EGR system please reference this page:

http://www.kennedydiesel.com/docs/Duramaz_LLY_LBZ_Emissions.htm