

2001 Dodge RAM 3500 PICKUP

Submodel: QUAD CAB | Engine Type: L6 | Liters: 5.9

Fuel Delivery: FI | Fuel: DIESEL

DTC Code P0230

DTC Code:

P0230

Description: Fuel Pump Primary Circuit Malfunction

Probable Causes:

1. Sensor or solenoid faulty
2. Connector terminal contact is damaged or corroded
3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
4. Update control unit software - Check for the latest control unit update
5. Powertrain or Engine Control Module faulty