

2000 Dodge RAM 3500 PICKUP

Submodel: | Engine Type: L6 | Liters: 5.9

Fuel Delivery: FI | Fuel: DIESEL

DTC Code P1693

DTC Code: P1693

Description: Fault In Companion Module

Probable Causes:

1. Update control unit software - Check for the latest control unit update
2. Powertrain or Engine Control Module faulty
3. Battery voltage low