

## 2005 Dodge RAM 2500 PICKUP

Submodel: | Engine Type: L6 | Liters: 5.9

Fuel Delivery: FI | Fuel: DIESEL

---

### DTC Code P1652

---

**DTC Code:**

P1652

Description: Serial Communication Link Malfunction

**Probable Causes:**

1. Update control unit software - Check for the latest control unit update
2. Powertrain or Engine Control Module faulty
3. Battery voltage low