

## 2005 Chevrolet SILVERADO 2500 HD

Submodel: | Engine Type: V8 | Liters: 6.6

Fuel Delivery: FI | Fuel: DIESEL

---

### DTC Code P0404

---

**DTC Code:**

P0404

Description: Exhaust Gas Recirculation Control Circuit  
Range/Performance

**Probable Causes:**

1. Sensor or solenoid faulty
2. Connector terminal contact is damaged or corroded
3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
4. Update control unit software - Check for the latest control unit update
5. Powertrain or Engine Control Module faulty
6. Exhaust leaks or restrictions
7. EGR components clogged, dirty or leaky
8. EGR valve damaged/defective