

## 2001 Dodge RAM 3500 PICKUP

Submodel: QUAD CAB | Engine Type: L6 | Liters: 5.9

Fuel Delivery: FI | Fuel: DIESEL

---

### DTC Code P0522

---

**DTC Code:**

P0522

Description: Engine Oil Pressure Sensor Circuit Low Voltage

**Probable Causes:**

1. Sensor or solenoid faulty
2. Connector terminal contact is damaged or corroded
3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
4. Update control unit software - Check for the latest control unit update
5. Powertrain or Engine Control Module faulty
6. Battery voltage low
7. Fluid levels - Check engine and transmission oil level or manually check oil pressure readings